



NTM No 09 of 2020

28/02/2021

NOTICE TO MARINERS

Pipeline Buoy – Temporary Alteration to Light Characteristic

Mariners are advised that the Light Characteristic of the Pipeline Buoy AtoN; position 56° 22.530' N 003° 20.880'W has been temporarily altered to; Q R, until further notice.

Harbour Manager
Perth Harbour (Operated by CalMac Harbours)

Perth Harbour Office
01738 624 056 perth.harbour@calmac.co.uk