

NTM No. 7 of 2023 10/01/2023

NOTICE TO MARINERS

Perth Harbour

Friarton Lights not lit to charted character

Mariners are advised that the white light on <u>Friarton Bridge</u>, <u>Navigation Span (West Facing) Light QW in position 56°22.794'N 003°24.540'W</u> is reported not to be flashing as charted.

Mariners are advised that <u>Friarton Bridge</u>, <u>South Pier</u> (West Facing) <u>Light 2FR(vert) in position</u> <u>56°22.760'N 003°24.561'W</u> is reported as being extinguished.

Mariners are advised that <u>Friarton Bridge</u>, <u>North Pier (West Facing) Light 2GR(vert) in position</u> 56°22.824'N 003°24.522'W is reported as being extinguished.

Issued on behalf of the Harbour Master

Perth Harbour (Operated by CalMac Harbours)

Perth Harbour Office 01738 624 056 VHF 09 perth.harbour@calmac.co.uk